



PT. SCG LIGHTWEIGHT CONCRETE INDONESIA
JL. Surya Tekno KAV I-T1-3 Suryacipta City Of Industry,
Kutamekar, Ciampel Jawa Barat 41361 Indonesia
Phone : 0267-8610361
Fax : 0267-8610360
N.P.W.P : 31.567.302.0-433.000

PURCHASE ORDER

To : PT BARA TEKNIK INDONESIA
KAWASAN PERGUDANGAN TAMAN
TANGERANG SELATAN
Indonesia

PO No. : 4021012182
PO Date : 19.04.2022
PO Currency : IDR

Phone : 021 75880130
Fax :
N.P.W.P :

Please supply the following item



No.	Material Code	Item Description	Qty	Unit	Delivery Date	Unit Price	Total Amount	Discount
10		Additional Job Repair Valve DN25 PN40	2	PC	09.05.2022	3,500,000 / 1	7,000,000	0

Delivery To : PT SLCI
JL. Surya Tekno KAV I-T1-3 Suryacipta City Of Industry,
Karawang 41361 Indonesia

Total Prices 7,000,000
PPN (VAT) 770,000
Grand Total 7,770,000

Term of Payment : Credit 30 days after received bill

Remarks : PR 1021011807; additional job PO 4021011665
Spareparts cost to replace as per inspection report:
Gasket, packing set, seal nut, including lapping/polishing

Prepared By	Checked By	Approved By	Confirmed By (Vendor)
 Arfandi			

PURCHASE REQUEST CHECK APPROVAL

ITEM DESCRIPTION

PR Number : 1021011807
Total Price : IDR 7,000,000
Attachment : Click here (https://iot.scli.co.id/assets/lampiranpr/PR_1021011807.pdf)

Details PR

No.	Item	A	Material	Short Text	Quantity	Unit	Delivery Date	Plant	Matl.Group	PGR	Value
1	10	K		Additional Job Repair Valve DN25 PN40	2	PC	09.05.2022	PT SLCI	Supplies	DBA	7,000,000

Purpose:

[10] Additional Job Repair Blowdown Valve DN25 PN40 for Autoclave

GL: 523072

CC: 2011-10000

Dibuat Oleh,
90587(Taufik Hidayat)
2022-04-01 16:37:37

Checked by,
90156(Mochamad Nugrahaputra)
Approved at 2022-04-01
17:11:14

Budget Control,
90696(Mukhtar L)
Approved at 2022-04-05
16:56:02

Approved by,
90156(Mochamad Nugrahaputra)
Approved at 2022-04-06
11:28:59

PT. Bara Teknik Indonesia

PERGUDANGAN TAMAN TEKNO BSD
SEKTOR XI BLOK. E3 NO. 18
SERPONG-TANGERANG
Phone. 021-7588 0130/ 0131
E-maill : baratek.jkt@cbn.net.id

Tangerang, March 22, 2022

Messrs.
PT. SCG Lightweight Concrete

Attn. : Mr. Arfandi

Re : your inquiry

I would like referring to your inquiry of piping accessories and I would like to propose you the following :

No	Articles	Size	Qty	Price/ unit
838				
1	Gasket; seal nut & Packing set spare part for ARI-STEVI 2 way Control valve fig. 35.415	DN 25 (1")	1	Rp 3,500,000
839				
2	Gasket; seal nut & Packing set spare part for ARI-STEVI 2 way Control valve fig. 35.415	DN 25 (1")	1	Rp 3,500,000

Term : Loco at JAKARTA

P.P.N. : Shall be added on the top selling price

Hoping that our offer will suit your requirement and looking forward to hearing from you.

Thanks and best regard.

SUPIADI/ ANE



PT. BARA TEKNIK INDONESIA

Form No. : SDVLE-F-SPK-004-Rev.02

Kawasan Industri Dan Pergudangan Taman Tekno BSD Sektor XI Blok J3 No. 45
 Serpong - Tangerang 15134
 Phone : (021) 758 82427-28, (021)376 16073-74 Fax : (021) 758 80130
 Email : baratek@cbn.net.id

VALVE INCOMING INSPECTION

{ BLOWDOWN VALVE }

BASIC DATA

BARA Code No.	: BARA - SCG L	Job Given By	: Mrs. Anne
PO BARA No.	: 838	Date Received	: 14-03-22
Cust PO / WO No	: 4021011665	Date Inspection	: 14-03-22
Customer Name	: PT. SCG LIGHTWEIGHT	Receive Condition	: Leak

VALVE DATA

Manufacturer	: Ari Armaturen
Type/ Model	: BLOWDOWN VALVE
Figure No.	: 415
Serial No.	: -
Size - Class	: DN 25 PN 40

ACTUATOR DATA

Manufacturer	: Ari Armaturen
Type/ Model	: DP 32
Serial No.	: -

VALVE VISUAL

		CONDITION								RECOMMENDATION
√ : Describe problem Founded		Dirty	Scratch	Corroded	Damage	Erorded	Crack	Porosity	NOTE	
Valve	Body	√		√						Sunblasting / Painting
	End conection	√		√						Cleaned up
	Bonnet	√		√						Sunblasting / Painting
	Gasket			√						Replaced
	Plug	√	√							Machining / Polishing
	Stem	√	√							Polishing
Seat Condition	Sealing Contact	√	√							Lapping
	Seal Thread									
	Body Thread									
	Packing set				√					Replaced
	Bolt & Nut	√		√						Sunblasting / Painting

√ : Describe problem Founded







		Dirty	Scratch	Corroded	Damage	Erorded	Crack	NOTE	
Actuator	Stem	√							Cleaned up
	Diaphragm Housing	√							Painting / Cleaned up
	Spring	√							Cleaned up
	Seal nut				√				Replaced
	Yoke	√		√					Painting / Cleaned up
	Spring plate	√							Cleaned up
	Rubber / Diaphragm	√							Cleaned up
	Coupling	√							Cleaned up

RECOMMENDATION

√ Inspection √ Minor Repair Major Repair Pre Testing Junk

Notes :

Inspected by	: M. Sawatun	Checked	:	Acknowledged By	:
Date	:	Date	:	Date	:
Sign	:	Sign	:	Sign	:

<p style="text-align: center;">Stem</p>  <p style="text-align: center;">Stem was found dirty scrath need to machining/polishing</p>	<p style="text-align: center;">Stem</p>
<p style="text-align: center;">Seat</p>  <p style="text-align: center;">Seat was found dirty scrath need to lapping</p>	<p style="text-align: center;">Seat</p>
<p style="text-align: center;">Packing set</p>  <p style="text-align: center;">Packing set was found damage need to replaced</p>	<p style="text-align: center;">Packing set</p>
<p style="text-align: center;">Bold & Nut</p> <div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>Bora - SCGL CV - 838 - 3/22 Blowdown DN25 PN40 Inspection Before Repair</p> </div>  <p style="text-align: center;">Bold & Nut was found corroded dirty need to painting</p>	<p style="text-align: center;">Bold & Nut</p>
<p style="text-align: center;">Stem Actuator</p> <div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>Bora - SCGL CV - 838 - 3/22 Blowdown DN25 PN40 Inspection Before Repair</p> </div>  <p style="text-align: center;">Stem Actuator was found dirty need to cleaned up</p>	<p style="text-align: center;">Stem Actuator</p>
<p style="text-align: center;">Diaphragm Housing + Yoke</p> <div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>Bora - SCGL CV - 838 - 3/22 Blowdown DN25 PN40 Inspection Before Repair</p> </div>  <p style="text-align: center;">Diaphragm housing + yoke was found corroded dirty need to cleaned up and painting</p>	<p style="text-align: center;">Diaphragm Housing + Yoke</p>