## PT. Bara Teknik Indonesia

PERGUDANGAN TAMAN TEKNO BSD SEKTOR XI BLOK. E3 NO. 18 SERPONG-TANGERANG Phone. 021-7588 0130/ 0131 E-maill : baratek.jkt@cbn.net.id

Tangerang, Nov 05, 2024

Messrs. PT. SCG Lightweight Concrete

Attn. : Mr. Yoki

Re : your inquiry

I would like referring to your inquiry of piping accessories and I would like to propose you the following :

No	Articles	Qty	P	Price/ unit	
	SCG-11	<mark>.98</mark>			
1	Spare part for ARI-STEVI Blowdown fig. 35.415 Gasket; Stem: Packing set; oring act & seal nut	1	Rp	5,900,000	
2	Sandblasting; Lapping; Machining; Polishir	ng; clean up	1	Rp	4,850,000
3	Painting Cost		1	Rp	1,050,000
	SCG-11	.99			5.900.000
1	Spare part for ARI-STEVI Blowdown fig. 35.415 Gasket; Packing set; Seal nut & oring act	DN 25 (1")	1	Rp	4,500,000
2	Sandblasting; Lapping; Machining; Polishir	1	Rp	4,850,000	
3	Painting Cost	1,050,000			
					5.900.000

Term : Loco at JAKARTA

P.P.N. : Shall be added on the top selling price

Hoping that our offer will suit your requirement and looking forward to hearing from you.

Thanks and best regard. SUPIADI/ ANE

3	ARATEK			vasan Indu	stri Dan Perg \$ 21) 758 824	udangan T Serpong - T 27-28, (02 Email : bar	angerang 1 1)376 1607 atek@cbn.n	o BSD Se 5134 3-74 Fax. : et.id	ktor XI Blok : (021) 758 {		Form No. : BOYLE-F-SRV-004- Rev	
-					(	CONTRO	DL VALVE	)				
BASIC DA	- 976 (A)		NI CCCI			and dra						
BARA Code PO BARA N		1198	CV-SCGL							: Mrs. Ane : 21-10-24		
Cust PO Se		2200					Date Ins			: 24-10-24		
Customer	Name :	PT. SCG	LIGHTW	/EIGHT			Receive	Conditio	n	:		
VALVE DA	ATA		내야뢛	いたった		Maple 1	1912-14	Trail and		and share		
Manufactu Type/ Moc Figure No. Serial No. Size - Class	del : : :	ARI ARI BLOW I N/A N/A DN 25 I		N								
ACTUATO	and a second		a shingan'		A to be and the	ne sin te day				The second state of the second	ONER DATA	
Manufacturer : ARI ARM. Type/ Model : DP 30 Serial No. : N/A Power : Angin Signal : N/A			MATURE	N			Manufacturer Type/ Model Serial No. Power Signal			:	N/A	
						and the state of the state of the	VISUAL					
V	: Describe problem Fo	undad				COND	ITION				RECOMMENDATION	
v	The second product of a second second second	unded								NOTE		
	Valve		Dirty	Scratch	Corroded	Damage	Erorded	Crack	Porosity	NOTE	Condelecting (Deleting	
Body End cone	oction				V V			_	-		Sandblasting/Painting Sandblasting/Painting	
Bonnet	ection				V V						Sandblasting/Painting	
Gasket			1 <u></u>		V	V					Replaced	
Plug			V	V		v					Lapping/Machining	
Stem						V					Replaced	
	Sealing Contact		V	V				-			Lapping/Machining	
Seat	Seal Thread		52	823		14	-		-	2 <b>2</b>		
Condition	Body Thread		-	-	-	-	-	-	-	-	-	
Packing s						V					Replaced	
Bolt & Ni	ut		V	· · · · · · · · · · · · · · · · · · ·	V						Sandblasting/Painting	
V	: Describe problem Fo	unded	·	·			0				<u>.</u>	
	Actuator	Stration 1	Dirty	Scratch	Corroded	Damage	Erorded	Crack	CINES (1)	NOTE		
Stem		10000	V	V							Polishing/Machining	
	m Housing				V						Sandblasting/Painting	
Spring			V								Cleaned up	
Seal nut						V					Replaced	
/oke			V		V						Painting	
pring pl	ate		V		٧						Painting	
Coupling			V		٧						Painting	
Dring act			-			٧					Replaced	
Diaphrag	m		V								Cleaned up	
											1 <del></del>	
			L	I					L			
			"A Provide		R	ECOMM	ENDATIO	N				
V	Inspection	Minor Re	epair	V	Major Repa	air		Pre Testir	ng		Junk	
Inspected b	y : M. Sa	watun		Checked	;					Acknowled	dged By	
Date : 24-10-24 Date : Sign : Sign :						Date Sign						

Seat	Seat				
Seat was found dirty,scratch need to machining, lapping					
Packing set	Packing set				
BARA-CV- SCG CV-108 - 10/24 DN 25 PN 40 Inspection Bepre Repor damage need to replaced					
Spring	Spring				
BARA-CV- SCG CV-1198-10/24 DAV 25 PN 40 Inspection Before Repar Spring was found dirty need to cleaned up					
Stem Actuator	Stem Actuator				
BAPA-CV - SCG CV-1198 - 10/24 DN 25 PN 40 Inspection Before Refair Unspection Before Refair Unspection Before Refair Unspection Before Refair					
Diaphragm Housing	Diaphragm Housing				
SMA-CV-SCG CV-IIBB-ID/34 DN 25 FW ICO Inspection Before Paper Image: Hor CV-SCB DN 25 FW ICO Inspection Before Paper   Diaphragm housing was found corroded need to sandblasting/painting					

<b>P</b>	ARATEK			asan Indus Phone : (02	21) 758 8242	udangan Ta erpong - Ta 27-28, (021 Email : bara	aman Tekno angerang 13 )376 16073 atek@cbn.no	9 BSD Sek 5134 -74 Fax. : et.id	tor XI Blok . (021) 758 8		<u>Form No. : BOYLE-F-SRV-004- Rev 0</u>		
					(	CONTRO	LVALVE						
BASIC DA	TA		Way Sa			1 Section							
ARA Cod		BARA-C 1199	V-SCGL				Job Giver Date Rec			S40 (34)	Mrs. Ane 21-10-24		
O BARA N		1155					Date Insp			: 2	24-10-24		
ustomer		PT. SCO	LIGHTW	EIGHT			Receive (	Condition	า	:			
VALVE D	ATA				All a start				THE NEW YORK				
Manufactu Type/ Moo Tigure No. Serial No. Size - Class	del : :	ARI ARI BLOW I N/A N/A DN 25 I		N									
ACTUATO				著語が					ling and	POSITIO	NER DATA		
Manufacturer : ARI ARMA Type/ Model : DP 30 Serial No. : N/A Power : Angin			MATURE	N			Manufacturer : Type/ Model : Serial No. : Power : Signal :			:	N/A		
Signal		N/A					VISUAL			in the second second			
						COND	ITION				RECOMMENDATION		
V	: Describe problem F	ounded											
	Valve		Dirty	Scratch	Corroded	Damage	Erorded	Crack	Porosity	NOTE	<u> </u>		
Body			V		V						Sandblasting/Painting Sandblasting/Painting		
ind cone	ection		V		V						Sandblasting/Painting		
Bonnet			V		V	V			-		Replaced		
Gasket			V	V		v					Lapping/Machining		
Plug			V	V							Polishing/Machining		
Stem	Sealing Contact		v	V							Lapping		
Seat	Seal Thread		-	-		ш:	-	<b>H</b> 0	-	-	-		
Condition	Body Thread		-			-	-	-	-	-	17.		
Packing						V					Replaced		
Bolt & N			V		V						Sandblasting/Painting		
											P		
	: Describe problem F	ounded											
<u> </u>	Actuator	ounded	Dirty	Scratch	Corroded	Damage	Erorded	Crack		NOTE			
Stem	Attuitor		V	V							Polishing/Machining		
	gm Housing			V	V						Sandblasting/Painting		
Spring	Burnorasing		V								Cleaned up		
Seal nut						V					Replaced		
Yoke			V		V						Painting		
Spring p	late		V		V						Cleaned up		
Coupling	g		V		V						Cleaned up Replaced		
Oring ac						V					Cleaned up		
Diaphra	gm		V		-								
				-	-				1				
				1	1	1	1						
S. Samul					F	RECOMM	ENDATIO	N					
V	Inspection	Minor F	tepair	V	]Major Rep	air		Pre Testi	ng		Junk		
Inspected	by : M.S	Sawatun		Checked	:					Acknowled	dged By		
Date : 24-10-24 Sign :				Date : Date Sign : Sign									

Seat	Seat					
Seat was found dirty,scratch need to lapping						
Packing set	Packing set					
BAPA-CV- 5C6 CV-1199-10/24 DAV 25 PN 40 Inspection Before Refue Macking set was found damage need to replaced						
Spring	Spring					
BARA-CV - SCG CV-1199 - 10/24 DAV 25 PAV 40 Inspection Before Report Spring was found dirty need to cleaned up						
Stem Actuator	Stem Actuator					
BARA-CV - 5CG CV - 1199 - 10/24 DN 25 PN 40 Inspection Before Repair polishing/machining						
Diaphragm Housing	Diaphragm Housing					
With a set of the set of						

.



## TO WHOM IT MAY CONCERN

This serves to confirm that **PT. BARA TEKNIK INDONESIA** is an authorized distributor and stockist of **ARI-ARMATUREN** products for the area of Java, Indonesia.

**ARI-ARMATUREN S.E.A./GERMANY** will provide full supports to **PT. BARA TEKNIK INDONESIA** to ensure them providing assistance and support to all our valued customers in a professional manner.

Validity of this letter: 02.01.2024 to 31.12.2024

For and on behalf of **ARI-ARMATUREN S.E.A.** 

Ken Wong General Manager – ARI S.E.A