Display Purchase Req. 1021013588

Document Overview On 🛛 🗅 🎲 🖆 🚺 🖆 Personal Setting

2010 PR frm MRP/CBP Header						1001	100		-					
							Default V	alues						
Requisn Date Status	Item A I	Material	Short Text		Quantity	Unit	Delivery Date	Per	Requisnr.	Material Group	Plant	Stor. Loc.	PGr	Total Value
03.07.2023	10 F		Feed End Head L	inings 16 Ro	1	ST	29.12.2023	1	Robby	Asset; AUC	PT SLCI		DBA	35,000,000
03.07.2023	20 F		Shell Linings 24 R		1	ST	29.12.2023	1	Robby	Asset; AUC	PT SLCI		DBA	520,000,000
03.07.2023	30 F		Discharge End Lin	nings 16 Row	1	ST	29.12.2023	1	Robby	Asset; AUC	PT SLCI		DBA	37,000,000
Item [10] Fe	ed End He	ad Linings 16 I	Rows/Set											
	ed End He ntities/Dat	ad Linings 16 es Valuati		Lesignment	Source o	f Sup	ply Status		Contact Pe	rson Texts	Delive	ry Address	Spec20	00 / SC
	ntities/Dat	es Valuati			Source o	f Sup	ply Status		Contact Pe	rson Texts	Delive	ry Address	Spec20	00 / SC
Material Data Qua	A	es Valuati Purpose:	Account A	ssignment			ply Status		Contact Pe	rson Texts	Delive	ry Address	Spec20	00 / SC
Material Data Qua Item Texts Item text Item text Item note	A	es Valuati Purpose:		ssignment			ply Status		Contact Pe	rson Texts	Delive	ny Address	Spec200	00 / SC
Material Data Qua Item Texts Item text Item text Item note Item note Item vext	A	es Valuati Purpose:	Account A	ssignment			ply Status		Contact Pe	rson Texts	Delive	ry Address	Spec200	00 / SC
Material Data Qua Item Texts Item text Item note	A	es Valuati Purpose: Project Rep	on Account A	ssignment			ply Status	Y	Contact Pe	rson Texts	Delive	ry Address	Spec20	00 / SC

Project Asset DETAIL Asset Project / Asset Name : Purpose : Department Cost Center : Maintenance : Start/ Finish : Original Amount : : Additional Amount 1: : Additional Amount 2: : Project/ Asset Number *) : : IO 201020000234 : * Filled by Accounting Project/ Asset Number *) : : IO 20102000234 :				
DETAIL Project/ Asset Name : Rubber Ball Mill #3 Purpose : Replacement lifter rubber Ball Mill #3 after running 7000 hours Department Cost Center : Maintenance Start/ Finish : Jan-2023 - Sep-2023 BUDGET . Annual Budget Additional Budget Original Amount : Re9850,000,000.00 Re-approved By Director Additional Amount 1 : Re-approved By Director			donesia	
Project/ Asset Name : Rubber Ball Mill #3 Purpose : Replacement lifter rubber Ball Mill #3 after running 7000 hours Department Cost Center : Maintenance Start/ Finish : Jan-2023 - Sep-2023 BUDGET Image: Annual Budget Additional Budget Original Amount : Rp850,000,000.00 Additional Amount 1 : Re-approved By Director Additional Amount 2 : . Project/ Asset Number *) : IO 201020000234	Project	Asset		
Project/ Asset Name : Rubber Ball Mill #3 Purpose : Replacement lifter rubber Ball Mill #3 after running 7000 hours Department Cost Center : Maintenance Start/ Finish : Jan-2023 - Sep-2023 BUDGET Image: Annual Budget Additional Budget Original Amount : Rp850,000,000.00 Additional Amount 1 : Re-approved By Director Additional Amount 2 : IO 201020000234	DETAIL			
Purpose : Replacement lifter rubber Ball Mill #3 after running 7000 hours Department Cost Center : Maintenance Start/Finish : Jan-2023 - Sep-2023 BUDGET		: Rubber Ball Mill #3	· · · · · · · · · · · · · · · · · · ·	
Department Cost Center : Maintenance Start/Finish : Jan-2023 - Sep-2023 BUDGET Annual Budget Additional Budget Original Amount : Rp850,000,000.00 Re-approved By Director Additional Amount 1 : Re-approved By Director Re-approved By Director Project/ Asset Number *) : IO 201020000234 * Filled by Accounting	•		ll Mill #3 after running 7000 hour	S
Start/ Finish : Jan-2023 Sep-2023 BUDGET Annual Budget Additional Budget Original Amount : Rp850,000,000.00 Additional Amount 1 : Re-approved By Director Additional Amount 2 : Re-approved By Director Project/ Asset Number *) : IO 201020000234				
Start/ Finish : Jan-2023 Sep-2023 BUDGET Annual Budget Additional Budget Original Amount : Rp850,000,000.00 Additional Amount 1 : Re-approved By Director Additional Amount 2 : . Project/ Asset Number *) : IO 20102000234	Department Cost Center	: Maintenance		
BUDGET Annual Budget Additional Budget Original Amount : Rp850,000,000.00 Re-approved By Director Additional Amount 1 : Re-approved By Director Re-approved By Director Additional Amount 2 : IO 201020000234 * Filled by Accounting				
Original Amount : Rp850,000,000.00 Additional Amount 1 : Re-approved By Director Additional Amount 2 : Re-approved By Director Project/ Asset Number *) : IO 201020000234				
Original Amount : Rp850,000,000.00 Additional Amount 1 : Re-approved By Director Additional Amount 2 : Re-approved By Director Project/ Asset Number *) : IO 201020000234	BUDGET	Annual Bu	ıdget	Additional Budget
Additional Amount 1 : Re-approved By Director Additional Amount 2 : Re-approved By Director Project/ Asset Number *) : IO 201020000234	Original Amount			
Project/ Asset Number *) : IO 201020000234 * Filled by Accounting	Additional Amount 1	:	Re-approved	By Director
	Additional Amount 2	:	Re-approved	By Director
Proposed By Acknowledged By Check By Approved By Hull Image: Check By Image: Check By Image: Check By	Project/ Asset Number *)	: IO 20102000234	* Fill	ed by Accounting
Proposed By Acknowledged By Check By Approved By Hull Image: Check By Image: Check By Image: Check By				
Had Da Da	Proposed By	Acknowledged By	Check By	Approved By
	Hauf	Josh	Mar	Omos
User User Superior Accounting Dept Director	User	User Superior	Accounting Dept	Director

а.

Template for the Capital expenditure budget 2023

									-		5,153,666,000			
ComCode	FiscalYear	BudgetName	Order Code	CE Code	CAPEX Code	StartDate (Format 1/1/2022)	EndDate (Format 31/10/2022)	Quantity	Unit	Useful Life	Budget Amount (IDR)	Currency	Group	Priority
2010	2023	Recondition Pipe water supply packing to Boiler (pipe 4" length 120 meter)	1	2	21A			1	UT	8	65,000,000	IDR	Turnaround & Maintenance	3
2010	2023	Radiator cooling system for hydraulic (Crane loading unloading; tilting #3; and tilting #1) 100Lpm	1	2	21A			3	UT	8	21,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Recondition Inverter WKB Machine	1	2	21A			1	LOT	8	103,000,000	IDR	Turnaround & Maintenance	2
2010	2023	Recondition Cable Orange Part Number : 13354310	1	2	21A			1	Roll	8	55,278,000	IDR	Turnaround & Maintenance	1
2010	2023	Recondition Cable Hijau Part Number : 13324551 Profinet	1	2	21A			1	Roll	8	27,888,000	IDR	Turnaround & Maintenance	1
2010	2023	Recondition; Backup Program and Update Firmware Controller Siemens WKB	1	2	21A			3	UT	8	25,000,000	IDR	Turnaround & Maintenance	2
2010	2023	Recondition Panel QMC Incoming LV MDB	1	2	21A			7	UT	8	15,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Asset Motor Lifter WKB Crosscutting Lammers 1TZ90011BB234FB4-Z	1	2	21A			1	UT	8	9,500,000	IDR	Turnaround & Maintenance	1
2010	2023	Recondition Master Controller Beckoff Twincat dan Dongle HMI Cimplicity	1	2	21A			1	LOT	8	55,000,000	IDR	Turnaround & Maintenance	2
2010	2023	Hydrant System	2	2	12A			1	LOT	8	1,300,000,000	IDR	Safety	1
2010	2023	Sand Dryer	2	4	04A			1	LOT	4	2,000,000,000	IDR	Product cost Saving	1
2010	2023	Slurry Pump MST 6x4D-MAH	1	2	21A			1	UT	4	24,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Slurry Pump MST 4x3C-MAH	1	2	21A			1	UT	4	44,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Aluminium Dosing Plant (New Design)	1	2	21A			1	LOT	4	150,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Rubber Ball Mill #3	1	2	21A			1	LOT	4	850,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Repainting Silo Rawmat	1	2	21A			1	LOT	4	100,000,000	IDR	Turnaround & Maintenance	3
2010	2023	Recondition Econimizer Boiler	1	2	21A			1	LOT	4	150,000,000	IDR	Turnaround & Maintenance	1
2010	2023	Recondition Company name (front gate), ceiling and main building	1	2	21A			1	LOT	8	150,000,000	IDR	Turnaround & Maintenance	2
2010	2023	Printer Dot Matrix LQ-2190	1	2	21A			1	UT	4	9,000,000	IDR		2

RUBBER BALL MILL #3 COST

No	No Items Quantity Unit						
1	FEED END HEAD LININGS	16	Rows	35,000,000			
2	SHELL LININGS	24	Rows	520,000,000			
3	DISCHARGE END LININGS	16	Rows	37,000,000			
4	INSTALLATION JOB	1	Lot	55,000,000			
	GRAND TOTAL						



Fw: Request Asset Replacement Rubber Ballmill

1 message

Damita Adhi Pratama <damitama@scg.com> To: "muhamadindarobby@gmail.com" <muhamadindarobby@gmail.com> Mon, Jun 26, 2023 at 2:17 PM

From: Mohamad Rizky <mohamadriz@scg.com> Sent: Monday, June 26, 2023 11:06 AM To: Damita Adhi Pratama <damitama@scg.com> Cc: Mukhtar Luthfi <mukhtar01@scg.com>; Rossita Sunatra <rossitas@scg.com>; Mochamad Nugrahaputra <mochamnu@scg.com> Subject: Re: Request Asset Replacement Rubber Ballmill

Dear Mas Damita,

Terlampir pengajuan AUC (Replacement Rubber Ballmill) dengan nomor IO 201020000234

Terima Kasih Best Regards, Rizky

From: Mukhtar Luthfi <<u>mukhtar01@scg.com</u>> Sent: Friday, June 23, 2023 4:20 PM To: Mohamad Rizky <<u>mohamadriz@scg.com</u>> Subject: Fw: Request Asset Replacement Rubber Ballmill

To Rizky

Tolong di proses ya

THank You Mukhtar


From: Vorapong Panavasu <voraponu@scg.com> Sent: Monday, June 19, 2023 5:29 PM To: Damita Adhi Pratama <damitama@scg.com> Cc: Mochamad Nugrahaputra <mochamnu@scg.com>; Rossita Sunatra <rossitas@scg.com>; Mukhtar Luthfi <mukhtar01@scg.com> Subject: RE: Request Asset Replacement Rubber Ballmill

Approved

VORAPONG PANAVASU President Director, SCG Lightweight Indonesia (SLCI) HP: (+62) 81218445555 E-mail: voraponu@scg.com

From: Damita Adhi Pratama <damitama@scg.com> Sent: Monday, June 19, 2023 5:21 PM To: Vorapong Panavasu <voraponu@scg.com> Cc: Mochamad Nugrahaputra <mochamnu@scg.com>; Rossita Sunatra <rossitas@scg.com>; Mukhtar Luthfi <mukhtar01@scg.com> Subject: Request Asset Replacement Rubber Ballmill

	G Lightweight Concrete In CIP) / Asset Requestion Form	donesia	
Project	Asset		
DETAIL Project/ Asset Name Purpose	: Rubber Ball Mill #3 Replacement lifter rubber Ba	ll Mill #3 after running 7000 hours	2
	: Maintenance : Jan-2023 - Sep-2023		
BUDGET Original Amount Additional Amount 1 Additional Amount 2			-
Project/ Asset Number *)	:	* Fill	ed by Accounting
Proposed By	Acknowledged By	Check By	Approved By
Haul	Cool	Minu	
User	User Superior	Accounting Dept	Director



Thank you

Best Regards,

Damita Adhi Pratama

Maintenance Engineer

PT. SCG Lightweight Concrete

This e-mail contains legally protected intellectual property right and confidential information. If you are not the intended recipient, please immediately delete this e-mail from your system and notify the sender. Any unauthorized usage of this e-mail may be subject to available legal proceeding. This e-mail may contain personal opinion of the author or information that does not relate to the business of The Siam Cement Plc., its affiliates and associates ("SCG") for which SCG shall not be liable. It is advisable that all e-mails be scanned by reliable virus protection software. SCG bears no responsibility for any damage possibly incurred by this e-mail.

This e-mail contains legally protected intellectual property right and confidential information. If you are not the intended recipient, please immediately delete this e-mail from your system and notify the sender. Any unauthorized usage of this e-mail may be subject to available legal proceeding. This e-mail may contain personal opinion of the author or information that does not relate to the business of The Siam Cement Plc., its affiliates and associates ("SCG") for which SCG shall not be liable. It is advisable that all e-mails be scanned by reliable virus protection software. SCG bears no responsibility for any damage possibly incurred by this e-mail.

This e-mail contains legally protected intellectual property right and confidential information. If you are not the intended recipient, please immediately delete this e-mail from your system and notify the sender. Any unauthorized usage of this e-mail may be subject to available legal proceeding. This e-mail may contain personal opinion of the author or information that does not relate to the business of The Siam Cement Plc., its affiliates and associates ("SCG") for which SCG shall not be liable. It is advisable that all e-mails be scanned by reliable virus protection software. SCG bears no responsibility for any damage possibly incurred by this e-mail.

This e-mail contains legally protected intellectual property right and confidential information. If you are not the intended recipient, please immediately delete this e-mail from your system and notify the sender. Any unauthorized usage of this e-mail may be subject to available legal proceeding. This e-mail may contain personal opinion of the author or information that does not relate to the business of The Siam Cement Plc., its affiliates and associates ("SCG") for which SCG shall not be liable. It is advisable that all e-mails be scanned by reliable virus protection software. SCG bears no responsibility for any damage possibly incurred by this e-mail.

This e-mail contains legally protected intellectual property right and confidential information. If you are not the intended recipient, please immediately delete this e-mail from your system and notify the sender. Any unauthorized usage of this e-mail may be subject to available legal proceeding. This e-mail may contain personal opinion of the author or information that does not relate to the business of The Siam Cement Plc., its affiliates and associates ("SCG") for which SCG shall not be liable. It is advisable that all e-mails be scanned by reliable virus protection software. SCG bears no responsibility for any damage possibly incurred by this e-mail.

D 201020000234 - Replacement Rubber BM #3 (signed).pdf

RUBBER BALL MILL #3 COST

No	No Items Quantity Unit						
1	FEED END HEAD LININGS	16	Rows	35,000,000			
2	SHELL LININGS	24	Rows	520,000,000			
3	DISCHARGE END LININGS	16	Rows	37,000,000			
4	INSTALLATION JOB	1	Lot	55,000,000			
	GRAND TOTAL						