

90	404089.0 SET OF FAN MOTOR BEARING Net Price	1.00	SET	260.000	260.000
	Note			260.000	
				Subtotal	81.119.000
				PPn 11%	8.923.090
				Total (Rp)	90.042.090

3. Service Cost

Item	Description	Qty	UM	Price	Total
10	PREVENTIVE MAINTENANCE 4 FOR BS, BSD,BSV Net Price	1.00	EA	13.000.000	13.000.000
	Note			13.000.000	
20	REBEARING MAIN MOTOR BS/D,CS/D,CSD/X75KW Net Price	1.00	EA	3.500.000	3.500.000
	Note			3.500.000	
30	REBEARING FAN MOTOR ASD,BSD,CSD Net Price	1.00	EA	2.500.000	2.500.000
	Note			2.500.000	
40	RENTAL UNIT COMP 37KW 2 MINGGU Net Price	1.00	EA	16.000.000	16.000.000
	Note			16.000.000	
				Subtotal	35.000.000
				PPn 11%	3.850.000
				Total (Rp)	38.850.000

B. RECOMMENDED PARTS

Selain suku cadang termasuk jasa service yang bersifat mendesak pada bagian A, dibawah ini kami sarankan penggantian suku cadang termasuk jasa service yang bersifat optional untuk memastikan performance terbaik dari produk Kaeser:

Note :