

# PURCHASE REQUEST CHECK APPROVAL

## ITEM DESCRIPTION

[Download PDF! \(https://iot.slci.co.id/download\\_PR/1021015634\)](https://iot.slci.co.id/download_PR/1021015634)

**PR Number** : 1021015634

**Total Price** : IDR 8,000,000

**Attachment** : [Click here \(https://iot.slci.co.id/assets/lampiranpr/PR\\_1021015634.JPG\)](https://iot.slci.co.id/assets/lampiranpr/PR_1021015634.JPG)

## Details PR

No.	Item	A	Material	Short Text	Quantity	Unit	Delivery Date	Plant	Matl.Group	PGR	Value
1	10	K		Repair UPS APC SURTD1000XLi	2.000	LOT	31.10.2024	PT SLCI	Supplies	DBA	8,000,0

### Purpose:

[10] Repair for power backup IOT & Codesys Server

GL: 521101

CC: 2011-11900



<b>Dibuat Oleh,</b> 91709(Robby M) 2024-10-01 14:27:49	<b>Checked by,</b> 90715(M.Moechlis) <b>Approved</b> at 2024-10-03 10:00:27	<b>Budget Control,</b> 90696(Mukhtar L) <b>Approved</b> at 2024-10-08 13:55:59	<b>Approved by,</b> 90005(Vorapong Panavasu) <b>Approved</b> at 2024-10-08 19:26:31
--	--	---	---

Bandung, 14 Oktober 2024

Nomor : 24073S/STech/X/2024  
Perihal : Penawaran Maintenance UPS APC  
Lampiran : 2 Lembar

**Kepada Yth,  
Bapak Diki  
PT.SGC Lightweight Concrete Indonesia**

Dengan Hormat,

Sehubungan dengan adanya kebutuhan Maintenance Perangkat di tempat bapak **PT.SGC Lightweight Concrete Indonesia**, berikut ini kami berikan penawaran harganya :

No	Description	Qty	Case
1	Maintenance & Onsite Services UPS APC <b>SURT1000XLI</b> Checking Bank Power Checking & Reset Configuration Board Check Stabilize Power Checking seakring Checking Voltage Checking Board Part Checking & Healty system Power Calibration	2	Blanking & No Backup

Bad Identity

QS1123330223

No	Description	S/N	explanation
1	Board UPS SURT-1000XLI	QS1123330223	Good (tidak ada pergantian)
2	RBC 31 VRLA battery, 9Ah, 48VDC	BT-QS1123330223	Repleace (1 Catridge set)
3	SURT24XLBP BATTERY PACK	5S1534T05377	Repleace (2 Catridge set )

QS1230140568

No	Description	S/N	explanation
1	Board UPS SURT-1000XLI	QS1230140568	Bad (Pergantian & Pemasangan)
2	RBC 31 VRLA battery, 9Ah, 48VDC	BT-QS1230140568	Repleace (1 Catridge set)
3	SURT24XLBP BATTERY PACK	5S532T00369	Repleace (2 Catridge set )

Biaya

No	Description	Price	Qty	Total Price
1	Pengecekan Battery & Board APC	Rp 350.000	1	Rp 350.000
2	Battery Pack RBC	Rp 335.000	12	Rp 4.020.000
Sub Total				Rp 4.370.000
PPn 11%				Rp 480.700
Grand Total				Rp 4.850.700

① S/N QS1123330223

No	Description	Price	Qty	Total Price
1	Pengecekan Battery & Board APC	Rp 350.000	1	Rp 350.000
2	Battery Pack RBC	Rp 335.000	12	Rp 4.020.000
3	Board Maintenance (QS1230140568)	Rp 2.150.000	1	Rp 2.150.000
Sub Total				Rp 6.520.000
PPn 11%				Rp 717.200
Grand Total				Rp 7.237.200

② S/N QS1230140568

**Note :**

- Sistem Pembayaran Cash On Delivery
- Sudah termasuk pergantian part yang sudah disetujui oleh enduser
- Waktu pengerjaan 2-3 Hari kerja
- Waranty 1 tahun by vendor diluar dari kesalahan penggunaan dan kapasitas pemakaian
- SURT24XLBP = 2 Catridge = 8 Battery, SURT1000XLI = 1 Catridge = 4 Battery
- APC Certified
- Harga sewaktu waktu dapat berubah tanpa pemberitahuan sebelumnya mengikuti principle

Demikian penawaran harga ini kami sampaikan besar harapan kami untuk dapat bekerja sama dengan Perusahaan yang Bapak/Ibu Pimpin.

Hormat Kami,  
CV. Shanindo Technology

Renna Sisnawati

# Certificate of Achievement

## AUTHORIZED REGISTER PARTNER

APC by Schneider Electric recognizes

### SHANINDO TECHNOLOGY

as an Authorized Register Partner



Rob McKernan  
Senior Vice President, IT Global Channels,  
APC by Schneider Electric

Dec 14, 2021

Date

