

Display Purchase Req. 1021014679

Document Overview On Personal Setting

2010 PR frm MRP/CBP ▾ 1021014679

Header

Default Values




Requisn Date	Status	Item A I	Material	Short Text	Quantity	Unit	Delivery Date	Per	Requisnr.	Material Group	Plant	Stor. Loc.	PGr	Total Value
01.02.2024		10 K		Cam Follower Refeeding (Incl..	2	PC	22.02.2024	1	Robby	Supplies	PT SLCI		DBA	6,400,000

Item [10] Cam Follower Refeeding (Include Rubber) ▾


Material Data | Quantities/Dates | Valuation | Account Assignment | Source of Supply | Status | Contact Person | Texts | Delivery Address | Spec2000 / SC

Item Texts	A...	
• Item text	✓	Purpose: Replacement Broken Cam Follower in Refeeding Cutting Board (WKB Machine) GL: 523072 CC: 2011-11900
• Item note		
• Delivery text		
• Material PO text		

◀ ▶ Continuous-tex... ▾



2



Isometric View

1

3

No.	Description	Qty	Materials	Remark
1	Roller (ID: 105 x OD: 125 x width: 50 mm)	1	Polyurethan, shore 40-45	
2	Bearing 6204 2RS	2	Standard SKF	
1	Wheel	1	SS400	
			Scale: 1:1	Assy. No.
File	C:\Users\Tech\Documents\Project\SK\01.dwg	Date	23-08-16	Title
Dim	mm	Name	Sput Setyono	Referencing cutting board
Drawn				
Designed				
Checked				
Approved				

Cam follower