

Display Purchase Req. 1021014069

Document Overview On Personal Setting

2010 PR frm MRP/CBP

Header

Requisn Date St...	Item A I M	Short Text	Quantity	Unit	Delivery Date	P...	Requisitioner	Matl Group	Plant	Stor. Loc.	Purch. Grp	Total Value
10.10.2023	10 K	Repair Shaft TV-61	1	LOT	31.10.2023	1	Robby	Supplies	PT SLCI		DBA	1,800,000

Item





Item Texts A...


- Item text
- Item note
- Delivery text
- Material PO text

Purpose:
 Repair shaft TV-61 for Ready to Use Weighing Sand & Return Pump
 GL: 521101
 CC: 2011-11900


Continuous-tex...




SECTION A-A




SECTION B-B



SECTION C-C



DETAIL D



DETAIL E

3	KEY 10x70mm	1	RST 37	-
2	KEY 10x80mm	1	RST 37	-
1	SHAFT	1	VCN 150	SURFACE HARDEN 50 HRC
Pos	Description	Qty	Material	Remark
Client			Scale : -	Assy Dwg No : 2012-DWG-BMP-TK-01-100-002
Dim : mm	Name	Date	<p>TV 61 100</p> <h1>SHAFT</h1>	
Designed :	TAUFIQ	11-12-2017		
Checked :	YESSIKO	<i>[Signature]</i>		
Approved :	RULLY	<i>[Signature]</i>		
Group No:				
PT.SCG LIGHTWEIGHT CONCRETE INDONESIA	A4	2012-DWG-BMP-TK-01-100-002-D	Rev No : -	Page 11