

Display Purchase Req. 1021014245

Document Overview On | Personal Setting

2010 PR frm MRP/CBP ▾ 1021014245

Header

Default Values

Requisn Date	Status	Item A I	Material	Short Text	Quantity	Unit	Delivery Date	Per	Requisnr.	Material Group	Plant	Stor. Loc.	PGr	Total Value
07.11.2023		10 K		Repair Head Pulley BC 2	1	LOT	30.11.2023	1	Robby	Supplies	PT SLCI		DBA	5,500,000

Item [10] Repair Head Pulley BC 2

- Material Data
- Quantities/Dates
- Valuation
- Account Assignment
- Source of Supply
- Status
- Contact Person
- Texts
- Delivery Address
- Spec2000 / SC

Item Texts	A...	
• Item text	✓	Purpose: Repair Broken Head Pulley in Belt Conveyor Sand 02 [Rubber Roller] GL: 521101 CC: 2011-11900
• Item note		
• Delivery text		
• Material PO text		

◀ ▶ Continuous-tex...

