

# Display Purchase Req. 1021014246

Document Overview On Personal Setting

2010 PR frm MRP/CBP 1021014246

Header

Default Values

Requisn Date	Status	Item A	I	Material	Short Text	Quantity	Unit	Delivery Date	Per	Requisnr.	Material Group	Plant	Stor. Loc.	PGr	Total Value
07.11.2023		10	K		Repair Broken Tail Pulley BC 2	1	LOT	30.11.2023	1	Robby	Supplies	PT SLCI		DBA	4,900,000

Item [ 10 ] Repair Broken Tail Pulley BC 2

Material Data | Quantities/Dates | Valuation | Account Assignment | Source of Supply | Status | Contact Person | Texts | Delivery Address | Spec2000 / SC

Item Texts | A...

- Item text
- Item note
- Delivery text
- Material PO text

Purpose:

Repair Broken Tail Pulley in Belt Conveyor Sand 02 [Shaft]

GL: 521101

CC: 2011-11900

Continuous-tex...

