

Display Purchase Req. 1021014251

Document Overview On Personal Setting

2010 PR frm MRP/CBP

Header

Default Values

Requisn Date	St...	Item	A	I	M	Short Text	Quantity	Unit	Delivery Date	P...	Requisitioner	Matl Group	Plant	Stor. Loc.	Purch. Grp	Total Value
06.11.2023		10	K			8.2580.2 ECO-DRAIN 31 VARIO	1	PC	20.11.2023	1	Robby	Supplies	PT SLCI		DBA	5,914,000
06.11.2023		20	K			8.1813.00040 HOSE LINE	2	PC	20.11.2023	1	Robby	Supplies	PT SLCI		DBA	2,600,000

Item



Material Data | Quantities/Dates | Valuation | Account Assignment | Source of Supply | Status | Contact Person | **Texts** | Delivery Address | Spec2000 / SC

Item Texts	A...	
• Item text	✓	<p>Purpose:</p> <p>Replacement Broken Auto Drain System in Air Compressor 01 [Auto Drain & Output Hose already Broken and Caused Oil & Water Leak]</p> <p>GL: 523072 CC: 2011-11900</p>
• Item note		
• Delivery text		
• Material PO text		

◀ ▶ Continuous-tex...

