

























Display Purchase Req. 1021014256




Document Overview On    

 2010 PR frm MRP/CBP 1021014256





 Header

                   Default Values

Requisn Date	Status	Item	A	I	Material	Short Text	Quantity	Unit	Delivery Date	Per	Requisnr.	Material Group	Plant	Stor. Loc.	PGr	Total Value
07.11.2023		10	K			Pneu.Cylinder DSBC 63-50-PP...	1	PC	21.11.2023	1	Robby	Supplies	PT SLCI		DBA	3,500,000

 Item [10] Pneu.Cylinder DSBC 63-50-PPV-A  

Material Data Quantities/Dates Valuation Account Assignment Source of Supply Status Contact Person Texts Delivery Address Spec2000 / SC

Item Texts	A...	
•  Item text	✓	<p>Purpose:</p> <p>Replacement Broken Pneumatic Cylinder in Separator GSM</p> <p>GL: 523072</p> <p>CC: 2011-11900</p>
•  Item note		
•  Delivery text		
•  Material PO text		

◀ ▶ Continuous-tex...

STO

DNC-63-50-PPV-A

163403 D408

p max: 12bar

